

Category	Name of damage/facility	Address 1	Address 2	Describe Damage	Primary Cause of Damage	Approx. Cost
G	Fishing Pier (Boardwalk)	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 356	<p>Fishing Peir</p> <p>Strong winds and flooding from Hurricane Ian caused the following damages to the the property:</p> <ul style="list-style-type: none"> • Deck Structure: Complete loss of entire structure excluding concrete piles due to strong winds and flooding • Deck Appurtenances: Complete loss due to strong winds and flooding • Water Structure: Complete loss of entire structure due to strong winds and flooding • Power Structure: Complete loss of entire structure due to strong winds and flooding • Shade Structure: Complete loss of entire structure due to strong winds and flooding <p>Driven concrete piles remain (integrity of piles unknown)</p>	Hurricane	\$1,500,000
G	DivisionBldg_Description Yacht Club Complex Harbo	5815 driftwood parkway	Site Number 2	<p>Strong winds and heavy rains from Hurricane Ian caused the following damages to the property:</p> <ul style="list-style-type: none"> • roof structure: predominately exposed and damaged • Soffit: damaged due to strong winds during the storm • Exterior windows: generalized destruction, missing and damaged due to wind influence • Ceiling - part of ceiling collapsed and ceiling tiles dislodged and roofing insulation on floor • Structural wall: damaged due to flooding • Mechanical equipment (washing machines and dryers): severely damaged by water infiltration and flooding • Furniture: water damage due to flooding and water infiltration • Window awnings: destroyed by wind action <p>Note: Evidence of first floor flooding due to surge conditions-2'+</p>	Hurricane	\$500,000
G	Yacht Club Main Building	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 1	<p>Yacht Club Main Building</p> <p>Strong winds and heavy rains from Hurricane Ian caused the following damages to the the property:</p> <ul style="list-style-type: none"> • Canvas / aluminum awning at main entrance: destroyed by strong winds during the storm • Possible structural damage to architectural element over front walkway: beam east of main entrance shows potential cracking due to wind influence • Gutter at front entrance overhang: damaged due to strong winds • Soffit at front facade: damaged due to wind influence • Soffit and gutter along east breezeway: damaged due to fallen trees from strong winds • Window Panels on front elevation of building: missing, dislodged and shattered due to wind influence during the storm • Door Panel at front entrance: shattered due to wind influence during the storm • Portion of east roof of structure was tarped prior to storm event and slated for replacement • Minor water infiltration at main entrance <p>No futher interior damage</p>	Hurricane	\$320,000
G	Yacht Club Complex Mechanical Equipment Building	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 468	<p>Mechanical Equipment Building</p> <p>Strong winds and heavy rains from Hurricane Ian caused the following damages to the property:</p> <ul style="list-style-type: none"> • Roof structure and asphalt membrane around south roofline: damaged due to wind influence • Facia and soffit: Severe general damage through the roofline due to wind influence • Electrical switchgear: water infiltration throughout building damaging electrical switchgear <p>Evidence of significant water infiltration throughout structure</p>	Hurricane	\$300,000
G	Rotino Senior Citizen Main Building	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 3	<p>Strong winds and heavy rains from Hurricane Ian caused the following damages to the property:</p> <ul style="list-style-type: none"> • Roof shingles and soffit around building: damaged in isolated locations due to wind influence • Roof ridges: damaged and deformation caused by tree falling during the storm • Exterior light on top of roof: damaged due to wind influence and heavy rain • Vinyl flooring: minor water infiltration through doors damaging the floor 	Hurricane	\$250,000

Category	Name of damage/facility	Address 1	Address 2	Describe Damage	Primary Cause of Damage	Approx. Cost
G	Yacht Club Complex - Yacht Club Complex	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 357	<p>Beach Area Bathrooms</p> <p>Strong winds and flooding from Hurricane Ian caused the following damages to the the property:</p> <ul style="list-style-type: none"> • Roof shingles: moderate damage due to wind influence • Adjacent walkways: collapsed walkways due to storm surge • Facia and soffit: Severe general damage through the roofline due to wind influence • Foundation: Potential sinkhole adjacent to foundation in the northwest corner of building due to flooding • Exterior door: womens room door is jammed and inaccessible <p>Evidence of water infiltration throughout due to surge, two block courses high.</p>	Hurricane	\$150,000
G	Rotino Senior Citizen Addition - Activity Center	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 359	<p>Strong winds and heavy rains from Hurricane Ian caused the following damages to the property:</p> <ul style="list-style-type: none"> • Soffit along East facade: damaged due to wind influence • Antenna on roof: damaged by strong winds 	Hurricane	\$8,000
G	Yacht Club Complex - East Hallway	5819 Driftwood Pkwy, Cape Coral, FL 33904	Site Number 469	<p>East hall bath</p> <p>No interior or exterior damage noted from Hurricane Ian at this location</p>	None	\$0